ERRATA



N° 10190AERRA

Dear Customer,

With this INFINEON Technologies Errata Note we would like to inform you about the following

Erratum of Product Marking description in datasheet for BSR92P H6327

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Dr. Eckart Sünner

Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider

Registered Office: Neubiberg

Commercial Register: München HRB 126492

2019-05-28 Page 1 of 2

ERRATA



N° 10190AERRA

Erratum of Product Marking description in datasheet for BSR92P H6327

Products affected:	Sales name	SP number	OPN	Package
	BSR92P H6327	SP001101038	BSR92PH6327XTSA1	PG-SC59-3

▶ Detailed Change Information:

Subject: Erratum of Product Marking description in datasheet for BSR92P H6327

Reason: Product marking in datasheet shows nonconformance compared to the physical product marking on the device

Description: Old (Current)

■ LD

New (Correct)

■ LDs

▶ Impact of Change: NO change within the product specifications except marking description

NO change in quality and reliability

NO change in package outline dimensions

► Attachments: 3_cip10190.pdf Product datasheet BSR92P_Rev1.06

► Implementation Date: 2019-06-01

If you have any questions, please do not hesitate to contact your local Sales office.

2019-05-28 Page 2 of 2